

DATE 0207Z 14 DEC 63

~~TOP SECRET~~

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO : DIRECTOR

FROM : [REDACTED] 25X1

ACTION:

INFO : OPS 1-12

IMMEDIATE

IN--54481

TOR: 0245Z 14 DEC 63

TO IMMEDIATE [REDACTED]

INFO [REDACTED]

CITE [REDACTED]

0119

#3254

REF A [REDACTED] 8064

B [REDACTED] 0110

A. WE BELIEVE SSB DISCREPANCY REF B DUE IMPROPER MATING OF CANNON PLUG OR FAULTY TRANSCEIVER. NEW TRANSCEIVER BEING INSTALLED AND CANNON PLUG BEING REWORKED. FLIGHT CHECK AT ALTITUDE WILL NOT BE POSSIBLE PRIOR LAUNCH OF 3254.

B. IN VIEW HQS COMMENT PAR E REF A, PLS ADVISE IF YOU DESIRE AIR ABORT IN EVENT INABILITY TO RECEIVE SSB AND BIRDWATCHER AT ALTITUDE STILL EXISTS ON 3254.

END OF MESSAGE

25 YEAR RE-REVIEW

~~TOP SECRET~~

GROUP 1
Excluded from automatic
downgrading and
declassification